

Renew $\frac{1}{4}$ $\frac{510}{515}$ T255 R3W

Fd. G.L.O. Brass cap MKd " $\frac{1}{4}$ $\frac{510}{515}$ 1943"

with steel fence post set along side of

Stumps of 1943 Resurvey B.T.s as follows -

54" Now 60" N, $2\frac{1}{2}^\circ$ E, 48 $\frac{8}{8}$ ft.

Shows "S" & partial scribe on nearly
healed blaze.

14" Hemlock S, 89° E. 33 $\frac{0}{0}$ ft.

Now shattered stump - No scribe fd.

Wemk. New B.T.s -

6" I. cedar S, 85° E, 4 $\frac{8}{8}$ ft.

Mkd. " $\frac{1}{4}$ 515 CS BT"

13" Hemlock N, 17° E, 41 $\frac{2}{2}$ ft.

Mkd. " $\frac{1}{4}$ 510 CS BT"

This cor. lies on N.W. slope
approx. 60 ft. East of bench course
N.E. - S.W. in old logged unit with
Reprod. of Fir, Hemlock, cedar & maple.

August 8, 1966 FILED

V.P.T.

RECEIVED J.B.

J.H.

AUG 8 1966

V.P. Tracy

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

#100

*

C.S. File No. 54/27-71