

Renew $\frac{1}{4}$ $\frac{59}{516}$ T245 R3W

Fd. 1950 G.L.O. BRASS CAP, firmly set,
properly MKd BT's as follows -

10" Now 11" Maple N. $16\frac{1}{2}^{\circ}$ E. 5 $\frac{3}{4}$ ft,
Tipped over - alive - shows scribe "459"
on unhealed Blaze.

60" Fir (stump) S. 62° E. 38 $\frac{1}{2}$ ft,
shows healed Blaze - we set 6" ft.
Steel fence Post 2" ft. East of
cor. & MK. new B.T. -

16" Hemlock stump S. 66° W. 14 $\frac{1}{2}$ ft,
MKd. "4516 CS BT" (6 ft. high stump)

This cor. lies on gentle S.W.
slope in logged off unit.

Sept 12, 1967

U.R.T.
J.H.
D.W.

J. R. Tracy

86

O.K. J.W.D.

C.S. File No. 54/27

93