

59 | 510

Renew Sec. Cor. 516 | 515 T 245 R3W

Fd. 1950 ~~FILED~~ BRASS cap properly
MKd. & Bent over & Buried. We
Find O.B.T. as follows -

ORIG. 40" Fir N. $13\frac{1}{2}^{\circ}$ E. 112 ft.

Now only decayed remains of stamp
with fragmentary B&K scribe
visible on old axe blade. NO TRACE
of any other BTs found due to

logging. We reset BRASS cap in
PROPER position & MK. NEW BTs -

15" Yew S. $28\frac{1}{2}^{\circ}$ E. 37² ft.

Mkd. " T245 R3W S 15 CS BT "

7" Hemlock S. 51° W. 37⁴ ft.

Mkd. " S 16 CS BT "

11" Hemlock N. $7\frac{1}{2}^{\circ}$ W. 82⁵ ft.

Mkd. " T245 R3W S 9 CS BT "

12" Hemlock N. 14° E. 73⁷ ft.

Mkd. " T245 R3W S 10 CS BT "

Sept 11, 1967

V.R.T?
J.H.



V.R.T. Ray

158

D.W. J.W.B.

C.S. File No.

54/27-85