

Renew  $\frac{1}{4}$   $\frac{54}{59}$  T245 R3W

Fd. 1950 G.L.O. BRASS cap Buried & B.T. as follows -

26" FIR N.  $41\frac{3}{4}^{\circ}$  E, 14  $\frac{3}{4}$  ft.

Moved by Logging - should be 17  $\frac{9}{10}$  ft.

SCRIBE visible - Now STump.

18" Hemlock S.  $29\frac{1}{2}^{\circ}$  W, 50  $\frac{8}{10}$  ft.

Now STump - "S9 BT" scribe showing

This B.T. under Logging debris. Set

6 ft. Steel fence post along side

BRASS cap & MKdew B.T. -

58" FIR STump S.  $53^{\circ}$  E, 33  $\frac{1}{4}$  ft.

Mkd. "  $\frac{1}{4}$  S9 CSBT " also Weyenhueser

"W" Nail at Base. This cor.

Lies on Steep S.W. Slope 70 ft.

E. of creek 3 ft. wide course S.

IN clearcut unit.

Sept 14, 1967

V.R.T.  
J.H.  
D.W.

*V.R. Tracy*

#59

O.K. S.W.B.

C.S. File No. 54/27

87