

Renew $\frac{1}{4}$ cor. 527/526 T235 R2W
Fd. cor. stone mkd. " $\frac{1}{4}$ " 25' coll'd
for. in orig. field notes & O.B.T.S
25 follows -

orig. 8" now 14" cedar S. 54° E. 4 $\frac{1}{2}$ ft.
now snag - scribe visible on unhealed
blaze.

orig. 24" now 25" Fir S 70° W. 13 $\frac{2}{3}$ ft.
now snag - scribe "45" visible on
unhealed blaze - in place of cor.
stone set 1" I.P. & brass cap

mkd. "DOUG. CO. SURVEYOR'S OFFICE
1969 T235 $\frac{1}{4}$ 527/526 R2W" & Reset
stone alongside - MARK new B.T.S -

18" Hemlock N 76° E. 20 $\frac{1}{2}$ ft.
mkd. " $\frac{1}{4}$ 526 DCS BT"

48" D. Fir N. 68° W 24 $\frac{1}{2}$ ft.
mkd. " $\frac{1}{4}$ 527 DCS BT"

This cor. lies on steep
N.W. slope. This cor. is on
E.-W Lane-Douglas Co. Line.

July 24, 1969

V.R.T.
J.G.H.
V.D.P.

V.R. Tracy

#150

C.S. File No.

0.1
54/27-112