

Renew Sec. Cor. ^{510 511} 515 514 T255 R2W

Fd. C.S. Brass Cap properly MKd. (see
Ren. # 2 by B.B.I.) & BTs as follows -

ORIG. 11" Hemlock N. 27° E. 11³/₄ Ft.

Now Shattered & Decayed Stump. No scribe fd.

ORIG. 16" Hemlock S. 43° E. 19¹/₄ Ft.

Now snag - scribe visible on open blaze.

ORIG. 7" Now 14" Cedar S. 56° W. 22¹/₄ Ft.

2 live - Rescribed by B.B.I. & ORIG.

scribe visible on badly decaying

face. - No trace ORIG. N.W. BT -

Ren. # 2 BTs as follows -

24" cedar N. 80° W. 58¹/₂ Ft.

Now sawed stump - scribe visible.

16" Fir N. 57° E. 33¹/₄ Ft.

TURNED out & partially buried.

18" cedar S. 84° E. 51¹/₂ Ft.

2 live & in good cond. scribe visible

We MK. New BTs -

26" Hemlock N. 20° E. 59¹/₄ Ft.

Mkd. " T255 R2W S 11 CS BT "

14" cedar S. 69° W. 40³/₄ Ft.

Mkd. " T255 R2W S 15 CS BT "

No Trees available to MK.

June 15, 1967

83

J. R. Tracy

C.S. File No.

V.R.T.

J.H.

D.W.

54/27.12