

Review $\frac{1}{4}$ $\frac{56}{57}$ T255 R3W

Fd. 1944 G.L.O. BRASS CAP BROKEN
off 12" below cap & B.T.s as follows
O.A. 19.20" Now 24" FIR S. 81 $\frac{1}{2}$ ° W, 92 ft,
SCRIBE VIS. ON CHOPPED OUT BLAZE - alive
46" Now 48" FIR S. 23 $\frac{1}{2}$ ° W, 30 $\frac{1}{2}$ ft,
live - blaze pitched over - NO SCRIBE VIS.

1966 C.S. B.T.

22" I. CEDAR N. 29 $\frac{1}{2}$ ° W, 45 $\frac{8}{8}$ ft.

MKD. " $\frac{1}{4}$ S 6 C S B.T." alive & in good

COND. ^(for other old B.T.s)
(see Ren. # 119) set new

1" I.P. & BRASS CAP MKD. COUNTY

SURVEYOR'S OFFICE 1968 T255

$\frac{1}{4}$ $\frac{56}{57}$ R3W" in place of Remaining
pipe at point for $\frac{1}{4}$ COR.

This COR. LIES ON MODERATE SW.

SLOPE APPROX 470 ft. East of

CREEK COURSE, N.W. - ~~Deposit~~ old

BRASS CAP ALONGSIDE ~~BLAZE~~

Feb. 5, 1968,

U.R.T.
U.P.

A. R. Gray

134

C. S. File No. 54/27-125