

T245 534 | 535
Renew Sec. Cor. T255 531 52 R3W.

Fd. 6.60. Brass Cap MKd " T245 R3W

534 | 535
53 | 52 T255 1944 "with steel fence

Post set along side of Bent over R.

1944 B.T.s 25 follows —

60" Fir (STump) N. 33 1/4 ° E, 52 1/2 ft.

Shows "T245 R3W 535 BT" scribe on unhealed

Blaze.

12" Now 20" R. Cedar S. 79 ° E, 46 ft.

Shows good scar - Rescribed. "T255 R3W 52 CS BT"

6" Now 16" Fir S. 48 1/2 ° W, 40 3/4 ft.

48" Log lying against scar only top of scar

visible.

8" Now 14" R. Cedar (SNAG) N. 51 1/2 ° W, 37 1/2 ft.

Dead & Burned - NO scribe. WEMARK

New B.T.s —

6" D. Fir N. 10 ° E, 23 1/2 ft.

Mkd. "T245 R3W 535 CS BT"

17" R. Cedar N. 69 ° W, 35 1/2 ft.

Mkd. "T245 R3W 534 CS BT"

Cor. lies on moderate west slope

approx 120 ft west of top of spur.

Reset fence post along side Cap.

Sept. 15, 1966

U.R.T.
J.B.
J.H.
O.W.S.W. G. C. S. File No. 54/271 131