

Renew  $\frac{1}{4}$  cor. 514/513 T245 RIW  
Fd. cor. stone in place with only  
partial chise/mks on W. side -  
D.B.T.s follows -

orig. 36" now 40" Fir N. 33° E, 58 $\frac{1}{2}$  ft.  
alive - shows good scars

orig. 30" now 38" Fir N, 10° W, 18 $\frac{5}{8}$  ft.  
alive - shows good scars - 2<sup>nd</sup> cor.

point in place of stone set 1"

I.P. & BRASS cap MKd. "COUNTY  
SURVEYORS OFFICE 1970

T245  $\frac{1}{4}$  514/513 RIW" & reset old  
stone along side - MK. new B.T. -

13" cedar N. 53° E, 23 $\frac{1}{2}$  ft.  
MKd. " $\frac{1}{4}$  513 CS BT"

This cor. lies on very steep  
E. slope in old growth  
Timber.

June 1, 1970

V.R.T.  
V.D.P.

V.R. Tracy

D.V. W. B.  
J.W. B.

#106 /

C. S. File No. 54/27 194