

Renew $\frac{1}{4}$ COR. $\frac{515}{522}$ T245 RIW

Fd, 1962 C.S. BRASS cap & pipe ^{Ren#25}

Tipped over with root wad of
orig. N.W. B.T. and orig. S.W. B.T.

also face Down - our 1962 BT, a
7" now 8" W, FIR N. 5° E, 31 $\frac{1}{2}$ ft.

alive - spit with about $\frac{1}{2}$ of upper
Blaze hanging loose with scribe
MKs - Lower scar healed over -

Reset BRASS cap in proper
place & mk. New B.T.s -

6" W, FIR S. 25° E, 55 $\frac{1}{2}$ ft,

Mkd. " $\frac{1}{4}$ 522 CS BT "

10" D, FIR N. 73° E, 38 $\frac{1}{2}$ ft,

Mkd. " $\frac{1}{4}$ 515 CS BT "

This cor. Lies moderate S.W.
Slope approx 100 ft. S. of
Ridge Top course S.E.

April 13, 1970

VRT
JAH
VDP

V.R. Tracy

O.X.
J.W.O.

#91

C. S. File No. 54/27-209