

Renew Sec. Cor.  $\frac{511}{514} \frac{512}{513}$  T245 R2W

Fd. orig Cor Stone with 4 notches on South & 1 notch on East edges & 9 B.T.s as follows -

orig. 36" now 42" Fir N. 85° E, 22  $\frac{1}{2}$  ft.  
alive - bark scribed "T245 R2W 512 BT"

orig. ? " now 32" Fir S, 33° E, 34  $\frac{1}{2}$  ft.  
alive - shows good scar

orig 6" now 13" maple S, 38° W, 22  $\frac{1}{2}$  ft.  
alive - shows good axe scar - Record Fir,  
we Rescribe "T245 R2W 514 cs BT"

Probable orig. 8" now 15" maple N. 73° W, 38  $\frac{1}{2}$  ft.  
Record 18  $\frac{1}{2}$  ft. - face Down & under Logs  
shows scar & was Tagged. Apparent 30 link  
error. 2<sup>nd</sup> cor point in place of  
Rock set 1" I.P. & Brass cap MKd.

"COUNTY SURVEYORS OFFICE 1969"  
T245  $\frac{511}{514} \frac{512}{513}$  R2W " & reset Stone along  
side - MARK New B.T.s -

20" Hemlock N. 27° W, 29  $\frac{1}{2}$  ft.  
MKd. "T245 R2W 511 cs BT"

8" Hemlock N. 54° E, 28  $\frac{1}{2}$  ft.  
MKd. "T245 R2W 512 cs BT"

August 19, 1969

U.R.T.  
U.D.P.

#65 *P. Tracy*

C. S. File No.  $\frac{511}{514} \frac{512}{513}$  27-238