

Renew Sec. CoR $\frac{510}{515} \frac{511}{514}$ T245 R2W

Fd. OBT. 25 follows - see also Ren. #20

Orig. 30" Now 34" Fir S. 20° E. 21 8 ft

Now sawed stump - Mostly Buried in Log Landing. No Trace other Orig

BTs Due To Logging also

Find Weyerhaeuser Method BT -

40" Fir S. 86° W. approx 42° ft.

Down - Note for "W" Nail on under

Side - Plate still attached. - at

CoR. point as set from Orig BT -

set 1" I.P. & Brass cap MKd.

"COUNTY SURVEYORS OFFICE

1969 T245 $\frac{510}{515} \frac{511}{514}$ R2W" & set

6° ft. steel fence post 1° ft.

west of BRASS cap. MK. New BTs -

50" D. Fir N. 67° W. 60° ft.

Mkd. "T245 R2W S 10 CS BT"

40" D. Fir S. 78° W. 86° ft.

Mkd. "T245 R2W S 15 CS BT"

No other Trees available.

This CoR. lies on Log Landing,

60° ft. E. of old growth Timber

course N. & S. -

Aug 13, 1969

#22 V. R. Y. Ray

U.R.T
J.G.H.

S. File No.

54/27-246