

Renew $\frac{1}{4}$ cor $\frac{529}{532}$ T245 R2W

Fd. 1951 cad BRASS cap

Firmly set and in place 25

Determined from Remsing B.T.'s -

Orig. 40" FIR (SNAG) S. 11° E, 23 $\frac{1}{2}$ ft.

BARK scribe still visible.

1951 56" FIR STUMP S. $42^{\circ}45'$ E, 24 $\frac{1}{2}$ ft.

scribe visible, - we set 6 $^{\circ}$ ft.

Steel fence post alongside BRASS

cap. There being no trees close

we set a $\frac{3}{4}$ " I.R. North 20 $^{\circ}$ ft.

& a $\frac{3}{4}$ " I.R. West 5 $^{\circ}$ ft from

$\frac{1}{4}$ cor. - This cor. lies on

NE slope in old logged area.

August 21, 1968

V.R.T.

J.F.H.

V.O.P.

V.R.T. Tracy

J.K.
J.W.B.

#69

C.S. File No.

54/27-254