

Renewal

$\frac{513}{529}$

T315 R2W

Found:

No trace of cor stone

OBT's

29" Fir Now snag S70E 13<sup>11</sup>

Batten Nothing visible

20" Fir Now 34' N40W 26<sup>4</sup>

Best scribe visible  $\frac{1}{4}$  S13 CS BT

Renewed:

IN Mound of stone 5' x 2<sup>5</sup>

Set Brass cap at  $\frac{1}{4}$  sec. cor. MKD

County Surveyors Office

T315 R2W

$\frac{1}{4} \frac{513}{524}$

1966

New Bearing Trees:

20" D. Fir S75<sup>1</sup>W 32<sup>9</sup>

Scribed  $\frac{1}{4}$  S24 CS BT

Reblazed & Rescribed

34" D. Fir N40W 26<sup>4</sup>

Scribed  $\frac{1}{4}$  S13 CS BT

Renewal #10  
B.R.I. 1931

7-8-66

~~9 MKD~~  
~~524~~  
TCE

#71  
O.K. J.W.B.

C.S. No. 54/28-30

DIETZGEN NO. 385-6