

Renewal

9/10
16/15

T315 R2W

Found:

30" Pine Now Down N 82° W 999' L
Scribe visible S9 RT
I Found distance to be 960'

30" Pine Now Stump S 73° E 468' L
Stump had part of old face
Lower face rotten

1 12" Pine N 89° E 642' L
No trace of this tree

Received:

Sat Brass cap at Sec cor M40.

County Surveyors Office

T315 R2W

99/510

316/515

1966

Went Bearing Trees

25" Pine N 82° W 98' L
Scribed T315 R2W S9 CS RT

29" Pine N 65° W 69' L
Scribed T315 R2W S9 CS RT

10" Cedar S 6° E 29' L
Scribed S15 CS RT

12 Cedar S 61° W 101' L
Scribed T315 R2W S16 CS RT

B-2-66

#87

OK J.W.B., C.S. No. 54/28-53

DIETZGEN NO. 385-6