

Renewal

218/517  
519/520

T312 R2W

Founds

30" Fir Now Down N50E 127<sup>2</sup>

30" Fir Now S170g N28E  
opened for scribbling 182<sup>2</sup>

6" Fir Now S20W 44<sup>2</sup>  
Shows good scar

6" Hemlock S48E 42<sup>E</sup>  
No trace of this tree

Renewed:

Set Brass cap at Sec. Com. Md.  
County Surveyors office

T312 R2W

218/517  
519/520

1966

New Bearing Trees

12" Cedar N 5 E 28<sup>E</sup>  
Scribed T312 R2W S17 CS BT

2 1/2" P. Fir N 62 E 19<sup>E</sup>  
Scribed T312 R2W S17 CS BT

12" D. Fir S 33 E 12<sup>E</sup>  
Scribed T312 R2W S20 CS BT

No good trees in  
NW 40 Quad, 8-5-66

JMB  
JCB  
JCB

\*#96

OK J.W.B.

C.S. Flanagan 5/28/65

DIETZEN NO. 385-6