

Renewed

~~532~~/533

T305 R2W

Found

10" D. Fir N4W18" N50E 38²

shows good Scar

36" D. Fir N4W24W N5W 26²

Scribe Marks visible but not legible.

Renewed:

Set Brass cap at sec cor. M50,
county Surveyors office

T305

~~532~~/533

1R

2

5A

W

T315

1966

New Bearing Tree

22" D. Fir N26W 33²

Scribed T305 R2W S32 CS BT

8-25-66

JMM
FMM
TCC

T311-T312W

582

*

C.S. File No. 54/28-66

DIETZEN NO. 385-6