

Renewal

$\frac{38}{9}$

T305 R2W  
T315 R2W

Found:

27" Cedar now 20" N20W 11 1/2  
Poor shape  
Scribe visible 1/4 S"

18" D. Fir now 25" South 6 1/2  
Shows faint scar

Renewed:

Set Brass cap at 1/4 cor MKR

County Surveyors office

T305

$\frac{1}{4}$   $\frac{588}{24}$  R  
W

T315

1966

DIETZGEN NO. 385-6

New Bearing Tree.

4" Hemlock N30 E 20 1/2

Scribed 1/4 CS RT

Re blazed & Rescribed

25" D. Fir South 6 1/2

Scribed 1/4 S4 CS RT

9-1-66

#80  
O#129-T31-2

C.S. No. 54/28-67