

Renewal # 55-131-3

11
12/7

T315 R3-2W

Found:

32' D Fir	N 29 E	50°
Shows good scar		
29' D Fir	S 16 E	76°
Shows good scar		
31" Laurel	N 11 W	25°
Scribe visible	T315 R3W S12 BT	


(New BTs)

6" Hemlock New B'	S 33 W	85°
Scribe visible	S 12 BT	
9" Chinquapin New 12"	N 55 W	15°
Scribe visible	S 1 R3W BT	
7" Chinquapin New 10"	N 66 E	109°
Scribe visible	S 7 R2W BT	

No trace of 2 P.R. Falls in skid Rd.

Remarks

Set Brass cap of sec cor after county surveyors office



1970

Note: This cor lies 215' south of closing cor 1/6/7 T315 R3-2W

#141-T31-2
#192 R3

D.K.
J.W.P.

3-25-70
~~_____~~
~~_____~~

C.S. File No. 54/28-100

DIETZEN NO. 388-6