

Renewal  
Found

$\frac{51}{512}$

T315 P6W1

No Trace of Fern Rd  
OBT's

10" D. Fir New snag S99W 31°

Tree had Beer opened and burnt?  
Reopened lower for scribe "T"

I find distance to be 258  
37" Fir stump N30E 26°

No Marks visible

#7 Renewal

7" Fir now down N-W 15°

Scribe Marks visible "1/4 S"

This tree pushed out by skid trail

By using the two orig. Bearings and  
one distance of 260 I renew this one

Renewed

Set Brass cap at 1/4 cor MKD,  
county Surveyors office

T315 P6W1

$\frac{51}{512}$

1966

New Bearing Tree

20" D. Fir 55E 63°  
Scribed 1/4 S12 65 BT

This cor lies in cut unit about  
300° FT East of Rd.

No Trees to Scribe in North Quad

9-21-66

*[Signature]*  
C.S.

#98

(Renewal #1)

X O.K. J.W.B.

C.S. File No. 54/31-5