

Renewal

510 | 511
515 | 514

T315 R6W

Found

12" D Fir Now 15" N40E 11°
Shows good Scar

14" D Fir Now Stump N30W 19°
opened Log for Scribing "BT"
Scribing very high None on Stump.

No trace of S.E. or S.W. Trees.

Also Past Scribed 510, 511, 514, 515

Renewed:

Set Brass cap at Sec cor MAR
County Surveyors office
T315 R6W

510 | 511
515 | 514

1966

New Bearing Trees:

22" D. Fir N51W 69°
Scribed T315 R6W 510 CS BT

25" D. Fir S8W 39°
Scribed T315 R6W 515 CS BT

5" D. Fir S37E 45°
Scribed T315 R6W 514 CS BT

This cor lies in cor of cut unit
No good Trees in S.E. Quad

9-29-66

J. W. B.
C. S.

DIETZEN NO. 385-6

○ #94

* O.K. J. W. B.

C. S. File No. 54/319