

Renewal

$\frac{332}{55}$

T315 R6W  
T325 R6W

16" Fir Now 21" N 11 E 27°  
 Tree had been opened scribe visible  
 Broken top  
 5" Fir Now 7" S 42 W 23°  
 Scribe visible  $\frac{1}{4}$  s"

Renewed

Set Brass cap at  $\frac{1}{4}$  sec cor. MRP  
 county surveyors office

T315 R6W

$\frac{1}{4}$   $\frac{332}{55}$

T325

1966

New Bearing Trees

22" D. Fir N 19 E 38°  
 Scribed  $\frac{1}{4}$  S 32 CS BT

17" D. Fir S 27 W 71°  
 Scribed  $\frac{1}{4}$  S 5 CS BT

This cor lies West of Panther  
 creek about 200'

10-28-66

*[Signature]*  
 C.S.

\* 93-732

\* 824

C. S. File No. 54/31-41