

Renewal

$\frac{54}{58}$

T313 R9W

Found

18" D. Fir cor Tree  
opened North side of Tree  $\frac{1}{4}$  S Found

19" cedar Now 26" S18E 26'

No Scribing found  
I find this Bearing to be S18W

8" cedar Now N80W 10'  
No Scribing found looks as though it  
has been axed off.

Renewed

Set Brass cap on North East side of  
cor Tree MKD

County Surveyors office

T313 R9W

$\frac{1}{4}$   $\frac{54}{59}$

1967

New Bearing Trees:

9" Cedar N 37 $\frac{1}{2}$  W 41'  
Scribed  $\frac{1}{4}$  S 1 E 27'

8" Cedar S 21 $\frac{1}{2}$  W 23'  
Scribed  $\frac{1}{4}$  S 9 E 27'

2-20-67

~~54~~  
~~52~~

\*54

C. S. File No. 54/52-4

DIETZGEN NO. 385-6