

Renewal

53/52

T313 R9W

Found: orig pts

16x12x10 stone $\frac{1}{4}$ cor W Face

10" Laurel Now 12" N52E 22 $\frac{1}{2}$

13T Scribe Visible

I Find this bearing to be N32E

16" Laurel N24W 17 $\frac{1}{2}$

Shows good Scar Rotten Center

I Find this Bearing to be N29W

By using cor stone and 2 dists
I Renew

Renewal

Set Brass cap at $\frac{1}{4}$ cor MKD
County Surveyors office

T313 R9W

$\frac{1}{4}$ 53/52

1967

New Bearing Trees:

6" Laurel N51 E 14 $\frac{1}{2}$
Scribed $\frac{1}{4}$ S2 CS RT

8" Laurel N 77 W 29 $\frac{1}{2}$
Scribed $\frac{1}{4}$ S3 CS RT

Note:
This cor lies 22 $\frac{1}{2}$ South of ridge
Tap.

2-21-67
[Signature]
C.S.

*500

C.S. File No. 54/32-5

DIETZEN NO. 385-6