

Renewal

$\frac{53}{510}$

T315 R9W

Found:

orig trees
6" Hemlock cor tree now 8"
opened for scribe "5"

8" Hemlock now 16" S9E 33
Scribe marks visible but mostly covered
I find this bearing to be S36E

16" Hemlock now 18" N36W 66
Scribe visible S3 1/2 BT
I find this bearing to be N63W

By using cor tree & 2 distances
I Renewal

Set Brass cap on North side of cor tree
MRP

county Surveyors office
T315 R9W

$\frac{1}{4} \frac{53}{510}$

1967

New Bearing Trees

12" Hemlock N72E 30 1/2
Scribed 1/2 S3 CS BT

Note:

I open tree for ring count which
places these trees about 1900 Ring to
close for accurate counts.

2-21-67

~~Handwritten signature~~

#58
*

C. S. File No. 54/32-6

DIETZGEN NO. 385-6