

Renewal

S15 / S14

T31S R9W

10" Fir saw Tree Now 5' stub  
opened for scribe "5" that "4" 14" visible  
on East Face West Face Rotten

8" D. Fir Now Rotten Stump S55E 14 5

No Trace of SW Tree

Renewed:

Set Brass cap on East Side of  
car-stub. MAR.

county Surveyors office

T31S R9W

$\frac{2}{9}$  S15 / S14

1967

DIETZGEN NO. 385-6

New Bearing Trees:

7" D. Fir Scribed  $\frac{1}{4}$  S45 W 18 7  
S 12 W BT

5" D. Fir Scribed  $\frac{1}{4}$  S14 N 28 1/2 E 14 2  
CS BT

2-23-67

*[Signature]*  
C.S.

#73

D. H. J. W. B.

C. S. File No. 54/32-8