

Renewal

10/11
15/19

T315 R9W

Found:

8" Yew Now 10" N 68 E 195
Scribe visible Pattern "S11" "R9"

8" P. Fir Now Down S 35 E 150
Scribe visible S 14 T315 R9W BT
I find this bearing to be S 32 E
8" P. Fir Not Found S 32 W 27'

10" P. Fir Now Stump N 85 W 290

By using 2 Bearings & 3 Dist. I
Renew

RENEWAL

Set Brass cap at sec cor MAD,
County Surveyors Office

T315 R9W

S 10 / S 11
S 15 = S 14

1967

New Bearing Trees

8" Red Oak S 28 W 242
Scribed T315 R9W S 15 CS BT

21" Cedar S 50 E 350
Scribed T315 R9W S 14 CS BT

18" P. Fir N 56 1/2 W 390
Scribed T315 R9W S 10 CS BT

11" Yew N 79 E 175
Scribed T315 R9W S 11 CS BT

2-23-67
J. W. B.
C.P.S.

DIETZGEN NO. 388-6

* J. W. B.

C.S. File No. 54/32-9