

Renewal 55 / 54 T315 P9W

Found:
orig Trees:

36" car tree Face on E+W

19" D. Fir diam 29" N53E 92
opened for Service "19"

No trace of SW BT

Renewed:

Set Brass cap on East side of
car tree MTD,

County Surveyors Office

T315 P9W

1/4 55 / 54

1967

New Bearing Trees:

6" Hemlock S20 1/2 W 16'-
Scribed 1/4 55 on BT

9" Cedar S27 E 19'-
Scribed 1/4 55 on BT

These Bearings & Distances are
From Brass cap which is about
30" East of center of car tree

3-6-67

C. S. File No. 54/32-24

DIETZGEN NO. 385-B

364

*