

Renewal (#2A) $\frac{6}{7} \frac{5}{8}$ T315 R9W

Found

18" cedar Down Burnt S 46 E 41 S
 Scribe visible T315 R9W

18" D.F.V. Burnt Slog S 55 W 32

30" D.F.V. Burnt Slog N 30 W 8 E

Did not find ~~any~~ pipe

Renewal

Set Brass cap at Sec cor MAD county Surveyors Office

T315 R9W

$$\begin{array}{r} 56 \ 55 \\ \hline 57 \ 58 \end{array}$$

1967

New Bearing Trees

7" Hemlock N 46 W 70³
 Scribed T315 R9W S 6 C S ST

21" Cedar Stamp S 58 E 49²

No other Trees, Tagged old Trees.

3-7-67

~~J. W. B.~~

#65

O. N. J. W. B.

C. S. File No. 54/32-28

DIETZGEN NO. 388-6