

Renewal

54 | 53

7315 R
7315 9
W

Found:

BRASS CAP MAP

U.S. General Land Office

54 | 53

T325 R9W

1917

30" D. Fir

S 81 W

55 ±

TA's stump washed out

30" D. Fir (S new) S 70 E

29 ±

Should find same

Renewal

New Bearing Trees

5" D. Fir

S 85 W

5 ±

scribed

54

50

BT

8" D. Fir

N 32 W

37 ±

scribed

T315

R9W

534

CS BT

No other Trees Available

Note:

This cap lies West of
HP 1917

3-15-67

J. C. B.

490

43 J. R. B. W. B.

C.S. No. 54/32-38

DIETZGEN NO. 388-6