

Renewal

1/16  
12/7

T31S R9-10W

Found

48" D. Fir New stump N24E 115<sup>5</sup>  
shows RT seat

36" D. Fir New stump S55W 9<sup>9</sup>  
spaced for scribble 42" T31S R10

No trace of SE or NW RTs or  
of any stone

Renewals:

Set Brass cap at Sec cor M50  
County Surveyors office

T31S

R 51 56 15  
10 512 57 9  
W 1967 11

New Bearing Trees

8" Hemlock S27W 25<sup>2</sup>  
Scribbled T31S R10W S12 CS RT

12" Hemlock South 29<sup>9</sup>  
Scribbled T31S R9W S7 CS RT

16" Fir stump N19W 28<sup>3</sup>  
Scribbled T31S R10W S1 CS RT

10 Cedar N41E 53<sup>3</sup>  
Scribbled T31S R9W S6 CS RT

3-20-67  
~~Handwritten scribbles~~

DIETZEN NO. 3885-6

\* 49 O.K. J.W.B.

C.S. File No. 522-44