

Renewal 57/58 T31S R9W

Found:

24" D. Fir Now still about 24"  
Scribed Partly visible N30E 7E  
Scribbled Partly over ground 1/4 "B"  
S.W. BT Now stump hole  
No trace of stump  
Also

40" D. Fir stump N73E 9E  
Scribed BT 1/4 28 T31 R9W  
(unrecored)

Renewal

Set Brass cap at 1/4 cor MHP  
county Surveyors office

T31S R9W

1/4 57/58

1967

New Bearing Tree

18" D. Fir stump N65W 97E  
Scribed 1/4 S 7 CS BT

No Trees Available

Note

This cap lies on steep south  
slope. Also it is approx. 80E East  
of small ridge + 250E West of  
ravine. NE of cor is head of  
ravine is a rock bluff.

3-22-67

*[Handwritten signature]*  
FWS  
CCS

DIETZGEN NO. 385-B

\* 105  
D. V. J. W. B.

C. S. File No. 57/32-49