

Renewal 31/32 T31S R9W

Found:

12" Laurel Now 15" N35E 21°
Face Rotten

6" P. Fir Now 10" N82W 32°
opened for Ex. be "BT"

No Trace of Stone

Renewal:

Set Brass cap at $\frac{1}{4}$ cor MAR
County Surveyors Office

T31S R9W
 $\frac{1}{4}$ S31/532
1967

New Bearing Trees

12" Live Oak N32W 27°
Scribed $\frac{1}{4}$ S31 CS BT

12" Laurel N34E 26°
Scribed $\frac{1}{4}$ S32 CS BT

Note:

This cor lies approx 261° North
of small creek on steep
South slope.

1-3-67
J.W.B.
406

DIETZGEN NO. 385-6

X 1104

O.V. J.W.B.

C.S. File No. 54/32-58