

Renewal  $\frac{16}{21} \frac{15}{22}$  T 313 R 9W

Found: Orig Traces  
 72" Fir Now snag (12") N50E 21 8  
 60" Fir Now snag (60") S 70W 57 4  
 60" Fir Now stump (60") N40W 72 (26)  
 This dist probably slope dist. The  
 found "5" on Buried Face  
 18" W Fir Now Rotten Stump S45E 85 2

Renewal

Set Brass cap at Sec 604 MKD.  
 County Surveyors office  
 T 313 R 9W

$\frac{516}{521} \frac{515}{522}$

New Bearing  $\frac{A67}{Traces}$

15" D. Fir N15E 5 4  
 Scribed T 313 R 9W 515 63 BT  
 6" D. Fir N75W 13 6  
 Scribed T 313 R 9W 516 63 BT  
 12" D. Fir S 67W 21 2  
 Scribed T 313 R 9W 521 63 BT  
 14" D. Fir S 40E 6 2  
 Scribed T 313 R 9W 522 63 BT

7-4-67  
 J. W. B.  
 J. W. B.  
 J. W. B.

DIETZEN NO. 385-6

\*106  
 \* O.O.K. J.W.B.

S. File No. 57/32-60