

Revernal

35

T315 R9W

Found:

Brass cap at $\frac{1}{4}$ cor 1450,
general land office

S35

R17

18" D. Fir now down NW 2 W 31 $\frac{1}{2}$
Tree very rotten

8" Maple now 14" N 25 E 27 $\frac{1}{2}$
Stems good Scar

Also:

orig. tree

36" P. Fir now 10" S 60 E 27 $\frac{1}{2}$
Scribe visible "5"

Revernal

New Bearing Trees

11" P. Fir NBOW 78 $\frac{1}{2}$
Scribed $\frac{1}{4}$ S35 cor RT

7-10-67

~~JMM~~
~~WCS~~
~~RT~~

512-1329

⊗ #120

C. S. File No. 54/32-68

DIETZGEN NO. 385-6