

RENEWAL

1/4 521  
528

T315 R9W

Found:

60" D. FIR NOW 60" STUMP CORNER TREE  
SHOWS SCRIBING of 1/4 S ON THE  
NORTH SIDE & 1/4 S 28 ON THE SOUTH  
SIDE

60" D FIR NOW 60" STUMP N 47 W 28 4 FT  
BADLY BURNT SHOWS NO SCRIBING

18" P. Fir now 18" snag S 60 E 28 1  
good bearing a dist but no scribbling

RENEWAL

SET A BRASS CAP ON THE NORTH  
SIDE OF THE CORNER STUMP MKD  
COUNTY SURVEYORS OFFICE

T315 R9W

521  
528

1967

NEW B.T.S:

6" D FIR S 7 E 21 1/2 FT  
SCRIBED 1/4 S 28 CSBT

50" D FIR N 47 W 44 1/2 FT  
SCRIBED 1/4 S 21 CSBT

4-28-67

FW  
CRW  
M  
32-73

131

O.K. J.W.B.

X.S. File No.