

Renewal

512/57
513/518

T315 R10-9W

Found:

Cor Tree NAW Stump
Shows good scars

50" D. Fir NAW 50" Stump N42E 35E
Shows good scars

40" D. Fir NAW 40" Stump S60E 39E
Shows good scars

10" D. Fir NAW 10" Stump S50W 43E
Prepared for Service "BT"

36" D. Fir NAW 36" Stump N52E 20E
Shows good scars

Renewal

P.E. lies 90° th ~~W~~ center of Stump

Set Brass cap on North side of cor tree
Stump M.D.

county surveyors office

T315

R 512/57 R
10 512/57 9
W 513/518 W

1967

Location Tag on 36" Fir Stump SW
COR on Sibley Trail

New Bearing Trees

12" Shingump 522E 133E
Scribed T315 R9W 518 CS BT

14" Hardlock 512W 176E
Scribed T315 R9W 513 CS BT

(No other trees available) S.G. 67

O.K. J.W.B.

C.S. File No. 54/32-78

DIETZGEN NO. 3885-6