

Renewal 512/57 T315 810-9W

Found:

22" P.F. New Stump S73W 33°  
Scribe visible 1/4 RT

Also unrecorded Iron P.F. at cor.

No trace of orig. Stone or  
Traces

Renewal

Set Brass cap at 1/4 cor MKD,  
County Surveyors office

T315

R 10 1/4 512/57 R  
W W

1967

New Bearing Tree

5" Hemlock S23W 30°  
Scribed 1/4 CS RT

26" Cedar Stump S12 1/2 E 37°  
Scribed 1/4 57 CS RT

Notes:

This cor lies in bottom of  
small ravine trending about North &  
South

St. B-67

(Over)

~~St. B-67~~

\*437 O.K. J.W.B.

U.S. File No. 54/32-81

DIETZGEN NO. 385-6

I renew this car by using  
E.S. Lebermanawsky's Renewal 1959  
Said Surveyor found orig  
stone at  $\frac{1}{4}$  cor.

This car recorded at road's  
county - IN FILE

**FILED  
RECEIVED**

**MAY 8 1967**

**COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE**