

Renewal

524 / 519  
525 / 530

T31S R10-9W

Found:

46" D Fir now 31" N 1/2 E 14'

Scribe visible 519 RT

Also 1948 Patteny nailed To Tree

24" Cedar now 21" S 31 E 26'

Scribe visible 530 RT

Etching apparently done with knife

I <sup>renewed</sup> Renewed this cor by using Latham's  
Renewal 1967. Said surveyor set this cor by  
using 2 aug trees which are not there at the time  
Hemlock 1967 25' E Hemlock NW 1/4  
one tree was a snag the other down.

Renewal

Set Brass cap at sec cor MKR.

County Surveyors Office

T31S

N 524 / 519 RT

10 525 / 530 9

W W

1967

DIETZEN NO. 385-B

New Bearing Trees

11" Hemlock S 72 W 42'

Scribed T31S R10W 525 CS RT

25" D Fir N 50 W 45'

Scribed T31S R10W 524 CS RT

NOTE - THIS CORNER  
PREVIOUSLY RENEWED  
TRICKS CO.

(SEE COPY IN FILE)

5-8-67  
~~James~~  
~~Tricks~~  
~~Co~~

X #136

O.K. J.W.B.

C.S. File No. 54/32-22