

Redwood

531 | 532 T31 R9W
T32

Found

8" Yaw N40W9" N11W 32° (Pan 31°)
Faint scribe visible "7" "3"

8" Yaw N40W8" N14E 26° (Pan 25°)
RU scribing Rotted off

Brass cap of Sec cor MKD
General land office

T31S R9W

531 | 532

1917

Redwood
Next Bearing Trees

21" D. Fir N83W 12°
scribed T31S R9W S31 C2 BT

38" D. Fir N89E 12°
scribed T31S R9W S32 C2 BT

Note:

This cor lies on steep north
slope approx. 80° south of small creek
& 60° west of slide creek.

5-11-67

[Handwritten signature]
J. W. B.

MKD
* 45-732-9
O.K. J. W. B.

C. S. File No. 54/32-94

DIETZEN NO. 386-B