

Renewal

$\frac{2}{11} / \frac{1}{12}$

T31S R9W

Found

24' Cedar now 29' N50E 23'
aged For Scribble "89"

36" Fir now 37" N70W 112
Shows good Scar

36" Fir now 42" S63W 396
I find this bearing to be S57W
Shows good Scar

No Trace of SE Tree

Renewed:

Set Brass cap at See for MAD,
County Surveyors office

T31S R9W

$\frac{57}{511} / \frac{51}{512}$

1967

Now Bearing Tree

8" W. Fir S26E 87'
Scribbled T31S R9W S12 CS 151

10-14-67

[Signature]

#512

X

O.K. J.W.B.

C.S. File No. $\frac{57}{32}$ -90

DIETZGEN NO. 388-6