

Renewal

S24
S25

T31S R9W

Found

orig. Trees

16" D. Fir NW 22 S25E 52±
Scrub visible N

16" D. Fir NW ~~22~~ (NW) 37±

I find this to be NW 1 shows good scars JSB

I believe this by using bearing and distance from 1st tree not being able to get two bearings to agree

Renewals

Set Brass cap at $\frac{1}{4}$ cor
County Surveyors office

T31S R9W

$\frac{1}{4}$ S24
 $\frac{1}{4}$ S25

1967

No new trees needed

10-15-67

[Signature]
EJS

* 50

D.K. J.W.B.

C. S. File No. 54/32-91

DIETZGEN NO. 385-G