

General

5
8

T315 R7W

Found

18" B. Oak NW 23" N22E 33Z
has rotten face

15" B. Oak NW down + rotten SSE 29Z
found fragments of scribing

Also Brass cap finally set ^{at factory} at 152

General land office

T315 R7W

$\frac{1}{4}$ $\frac{55}{58}$

1918

DIETZEN NO. 385-6

New Bearing Trees

14" D. Fir Scribed $\frac{1}{4}$ S5 N15W CS BT 18Z

20" D. Fir Scribed $\frac{1}{4}$ S8 S60W CS BT 13Z

Note: This cap lies in very old
E-W fence line

6-19-69

O.V.

W.B. 54
C.S. File No. 45/36 702 10

477