

Rental #36 31/32 T31S R7W

Found:

28" D. Fir now 28" H36E 12[±]
Scribed visible $\frac{1}{4}$ S32 CS RT
SW RT Lugs 2-

Found Brass cap Bent over
& under log.

DIETZEN NO. 385-6

Rental
Reset Brass cap at $\frac{1}{4}$ cor MAP
County Surveyors office
T31S R7W

$\frac{1}{4}$
S31/S32
1963

New Bearing Tree

18" D. Fir S70W 233⁶⁰
Scribed $\frac{1}{4}$ S31 CS RT

Notes:

This cov lies East of RD #32-7-6
in old clear cut unit.

S. 22-72
G.M.
G.M.

✓ #93

C. S. File No. 54/36. P.L. Ingram
-204