

21 22
2B/27

T315 RBW

Revised

Found

(orig)

22" D. Fir Now 36" SSE 30 1/2
No scribe visible

15" D. Fir Now 20" SWW 37 1/2
scribe visible "3" & other faint marks

4" Line oak Now stub N37E 15 1/2

28" D. Fir Now 45" N67W 59
(Record N25W 52)
No scribe found

No trace of stone

Revised

Set Brass cap at Sec cor M100
county Surveyors office

T315 RBW

521 | 522
528 | 527

1970

New Bearing Trees

10" D. Fir N 66 E 16 1/2
Scribed T315 RBW 522 CS BT

10" D. Fir N 26 W 34 1/2
Scribed T315 RBW 521 CS BT

Replaced & Rescribed

36" D. Fir SSE 20 1/2
Scribed T315 RBW 527 CS BT

20" D. Fir SWW 27 1/2
Scribed T315 RBW 528 CS BT

3-24-70

V460

0.11 1/2

C.S. File No. 54/38 - 33

DIETZGEN NO. 385-6