

Renewed

23 24
26 25

T 315 RBW

Found:

98" OBT's

98" D. Fir Now 43"
Bark Scribe Visible

S35W 16 1/2
T 315 RBW BT

6" Live oak Now 8"
Shows Scar

N15E 24 1/2

I find Bearing to be N20E
and distance to be 21 1/2

8" Maple Now 12"
Shows good Scar

S65E 23 1/2

14" D. Fir Now 24"
Bark Badly Burnt.

N38W 30 1/2

I find this bearing to be N29W
and distance to be 25 1/2

Also:

Distances all meet at point, but they
would have had to use slope distance
on the

8" Maple S65E 23 1/2
14" D. Fir N21W 30 1/2

No Trace of cor Stone.

Renewed:

By using 4 Distances & 2 Bearings I
set Brass cap at Sec. cor NAD.

County Surveyors Office
T 315 RBW
523 524
326 525
1967

Relocate & Rescribed:

24" D. Fir N 21 W 25 1/2
Scribed T 315 RBW 523 CS BT

8" L. oak N 20 E 24 E
Scribed T 315 RBW 524 CS BT

Note:

This cor lies on steep north slope
about 300' N from canal creek Rd.
Yellow Tag on Rd.

1-20-66

* #4
D.K. J.W.B.

C. S. File No.

1777
257/36-51

DIETZGEN NO. 3885-6

**FILED
RECEIVED**

JAN 20 1967

**COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.**