

Renewal

17/16
20/21

T315 RBW

Found:

Brass caps at sea cor MAD
County Surveyors Office

2115 RBW
317 514
310 521
1958

New Bearing Trees

34" R. Fir Now 34" N32 1/2 W 10 1/2
Scribed T315 RBW 517 CS BT

16" R. Fir Broken Dead S 53 W 33 1/2
Scribed T315 RBW 520 CS BT

6" R. Fir N35 E 56 1/2
Scribed T315 RBW 516 CS BT

OBT
10" Fir Now 22" S11 E 15 1/2
Shows good scar

Renewal

New Bearing Tree

22" D. Fir S44 W 36 1/2
Scribed T315 RBW 520 CS BT

Note

This cor lies 155° West of
the Putman Look out Rd.

1-12-66

J. W. B.
C. S.

Renewal 1958

*#34

O. H. J. W. B.

C. S. File No. 54/36

N

DIETZGEN NO. 3885-6