

Renewal

R 36 | 31 R T 31 S 1 2 8 W
S 1 | 6 W T 32 S R 7 4 B W

Found:

8" L. Oak now 13" S 78 E 10 3
opposed for scribe "7" "6" "2"
12" D. Fir now rotten stub S 79 S W 6 7 2
NOTE N 38 W

No trace of N E or S W Trees

Renewal

Set Brass cap at Township cor. M22
County Surveyors office

T 31 S

R 36 | 31 R
S 1 | 6 W

T 32 S

1966

New Bearing Trees

10" D. Fir S 72 W 33 5
Scribed T 32 S R 8 W 51 CS BT

12" D. Fir S 48 1/2 E 24 1/2
Scribed T 32 S R 7 W 26 CS BT

8" Live Oak N 59 E 16 6
Scribed T 31 S R 7 W 5 31 CS BT

6" Live Oak N 48 W 9 6
Scribed S 36 CS BT

This cor lies about 330° Ft East of
creek on steep west slope

DIETZGEN NO. 388-B

27-32-8
38 T 32-7
32-7
31-7
36-7

12-1-66
J.W.B.
C.S.

* O.K. J.W.B.

C.S. File No. 54/36