

Renewal

$\frac{15}{22}$

T322 R7W

Found  
OBTS

50" D. Fir New 50" N75W 32°  
Best Scribe visible 1/5

16" D. Fir New Down S45E 5°

Iron Pipe out of ground pulled  
when SE BT Fell.

Renewal

Reset 1 1/2" I.P.P. at 1/4 cor  
From NW BT

New Bearing Tree

7" Chironia 576W 17°  
scribed 1/5 522 CS BT

Renewal #18

11-3-67

~~Handwritten signature~~

FILED

RECEIVED

NOV 3 1967

COUNTY SURVEYOR  
DOUGLAS COUNTY, CO

D.K. J.W.B.

C.S. File No.

54/36-89

DIETZGEN NO. 3866-6