

Renew  $\frac{1}{4}$  COR. <sup>43M</sup> 525 T32S R7W

Ed. O.B.T.s follows -

orig. 30" Now 40" Fir North 4<sup>0</sup> ft.

Down - stump in place - "BT" BORN

scribe - No trace of OBT. to SE.

Due to roadway to creek - at

COR. point set 1" IP & BR 25 COP

Mkd. "COUNTY SURVEYORS OFFICE

1970 T32S  $\frac{1}{4}$   $\frac{524}{525}$  R7W" & MK.

New BTs -

50" D. Fir S. 5<sup>0</sup> E. 70<sup>8</sup> ft.

Mkd. " $\frac{1}{4}$  525 CS BT"

30" D. Fir N. 88<sup>0</sup> W. 9<sup>8</sup> ft.

Mkd. " $\frac{1}{4}$  524 CS BT"

This COR. lies under Log of a BT.

& approx 60 ft East of old Log.

Road - Best Route to COR -  $\frac{1}{4}$  miles

from Robert Dollar Logging Road

at Junction of Totten Creek.

March 11, 1970

URT  
J.F.H.  
V.O.B.

V.P. Tray

O.K.  
J.W.B.